

# ToolsOnAir-Support

[Portal](#) > [Knowledgebase](#) > [Knowledgebase just.in](#) > [just.in v2.x](#) > [AJA Corvid88 and Myricom 10GbE](#)

## AJA Corvid88 and Myricom 10GbE

Chris - 2018-05-25 - in [just.in v2.x](#)

We are seeing problems when using the AJA Corvid88 and the Myricom 10GbE card together in a Thunderbolt Sonnet Chassis, it can result in a Kernel Panic of the Mac Pro. We recommend to avoid this combination of cards in a MacPro with Sonnect Chassis.