

ToolsOnAir-Support

Portal > Knowledgebase > Knowledgebase just:in > just:in v2.x > AJA Corvid88 and Myricom 10GbE

AJA Corvid88 and Myricom 10GbE

Chris - 2018-05-25 - in just:in v2.x

We are seeing problems when using the AJA Corvid88 and the Myricom 10GbE card together in a Thunderbolt Sonnet Chassis, it can result in a Kernel Panic of the Mac Pro. We recommend to avoid this combination of cards in a MacPro with Sonnect Chassis.